SALES REPORT: CATERPILLAR D6T - SN RRK00### - Year 2013

This Report is a summary about observations cames out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: D6T

Family: LARGE TRACK TYPE TRACTOR

Serial Number: RRK00###

Order Number MU/MM: MU00851554

Construction year: 2013

Hour meter: 13663

General residual conditions Truck/Tyres: 80 %

Machine main application: Basic application

Machine availability date : 20/11/2026

Location: Coming in

Rating: ★★★☆☆

Public price: Ask

MACHINE CONFIGURATION

● Machine type Standard - GP ● Truck type XL ● Rops Close ● Steering Control Differential steering ● Blade PAT ● Ripper plant ● Tow Bar ● Air Conditioning system ● General Truck Residual 80% CARRO SISTEM ONE ORIGINALE CAT AL 80% DI RIMAMENZA ● 22000 Kg ● CE Mark ● CE Certificate ● EPA Tag ● Use and maintenance manual

MACHINE PHOTOS























GENERAL APPEARANCE

Painting Conditions:	Good
Main frame welds presence:	Non Presenti

- Counterweight conditions: Good

  Needs painting? : No
- Frame/Bumper conditions: Good
- Cabin / Door / Lock conditions: Good
- Technical compartment doors conditions: Good

Truck

- N/D 80
- N/D 78
- N/D 80
- N/D 70
- N/D 79
- N/D 70

Functionality

Engine & electrical system functionality

- N/D Turned off & still
- N/D Good
- N/D No
- N/D No
- N/D No

N/D	No
N/D	Good
N/D	Good
N/D	Good
N/D	Non Presenti
N/D	MANUTENZIONE ORDINARIA SCADUTA FA FARE

Functionality drive and rotation

N/D	Good
N/D	Good
N/D	Good
N/D	Good

Thrust group

N/D	Good
N/D	Good Presence of welding/cracks : No
N/D	Good
N/D	NA - Not applicable
N/D	Good
N/D	Poor
N/D	Good

N/D	No
N/D GIUCHI SU ATTACCO LAMA PAT AL TELAIO COMPATIBILI CON LE ORE BALESTRONE CON LEGGERO GIOCO	

Cabin and Tools

Conditions internal cabin:	Good
Lights & Windshield present issues:	Presents and functioning
Air contidioning & Filters conditions:	Presents and functioning
Back & side camera conditions:	Present and functioning
Annotazioni sul: VENTOLE RADIATORE ESTERNO RETRO CABINA ARIA CONDIZIONATA NON FUNZIONANO FILI SCOLLEGATI	

Check 81/2008

Glass conditions:	Excellent - no needs repair
Lights conditions:	Excellent - no needs repair
Condizioni specchietti:	Eccellente - non necessita riparazione
Stepladders & handrails conditions:	Good
Cameras conditions:	Excellent - no needs repair
Flashing conditions:	Present and functioning
Safety belt conditions:	Present and expired
Controls been modified:	No
Presence of Exclusion Control Lever:	No

If No, are control levers protected to accidental funcionality? : No

Are Tools Functional & Visible with tag:	Yes
Canopy completed and comes with keys and bolt:	Yes
All Pipes with no damage e/o scratches:	Yes
Batteries box shielded:	Yes
Acustic alarm works properly:	Yes
Boardwalk presence:	Present and functioning

Valutazione Macchina

★ **Non Funzionante (NF)**

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

★★ **Scarso (S)**

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

★★★ **Buono (B)**

La macchina si presenta in buone condizioni sia estetiche che di funzionamento.
Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

★★★★ **Molto Buono (O)**

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate.
Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova".
Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

★★★★★ **Eccellente (E)**

La macchina si presenta in condizioni eccellenti, prossime al nuovo.
Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating

★ **Not Working (NW)**

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

★★ **Poor (P)**

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

★★★ **Good (G)**

Machine is in good condition and operational, with no structural issues.
Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted.
Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

★★★★ **Very Good (VG)**

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours.
No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New".
Main components with 50/60% of life residue. Machine in security conditions.

★★★★★ **Excellent (E)**

Machine is in excellent condition, comparable to a new one.
Main components with 70/80% of life residue. Machine in security conditions.